

3 July 1963



STATINTL

Reference the adjustment work done [redacted] on July 2 - 3, it is the consensus [redacted] that the equipment was placed in as good a condition as possible at the time. Voltage drops and possible minor mechanical mal-adjustments existing at the time did not make it possible to give a final overall clearance of the quality of the operation of the [redacted] components.


STATINTL

STATINTL

STAT

Therefore [redacted] has been released as having performed all work that could reasonably requested of him at the time. This however is not to be construed as a final acceptance of the equipment. This final acceptance cannot be made until the mechanical and line voltage factors have been eliminated. This will be accomplished as soon as possible after which further checks will be made on the performance of your components.

STATINTL



STATINTL

cc: [redacted]

Orig - Addressee

1

1

1 - DC/TID

1 - TID/TAB

STATINTL

NPIC/TID/TAB [redacted] (3 July 1963)

STATINTL

Declass Review by NIMA/DOD

NPIC ROUTING SLIP

Approved For Release 2003/05/15 : CIA-RDP78B04747A000900050034-1

FROM: *TID/TAB*

DATE:

	TO	INITIALS	DATE	FOR YOUR													
				SIGNATURE	INFORMATION	COMMENTS	CONCURRENCE	APPROVAL	ACTION	SEE REMARKS BELOW	FILE	RETURN	SEE ME				
DIR																	
DEP/DIR																	
EXEC/DIR																	
ASST FOR OPS																	
ASST FOR ADMIN																	
ASST FOR P&D	<i>xv</i>																
CH/PSD																	
CH/PD																	
CH/TID																	
SIO/CIA (PID)																	
SIO/ARMY																	
SIO/NAVY																	
SIO/AF																	
LO/DIA																	
LO/NSA																	
REMARKS:																	

STATINTL

STAT

Approved For Release 2003/05/15 : CIA-RDP78B04747A000900050034-1